

To: Real Estate Department Partners Notice: RED-21-22

From: Real Estate Department

Date: April 12, 2021

Re: Range Hood Fire Suppressor Recall

It has come to the attention of IHCDA that there has been a recall of the **Stove Top Fire Stop** Rangehood Fire Suppressor **Model# 675-3D**.

These have been the most popular rangehood fire suppressors used on RHTC developments for years.

Please check the brand and model numbers of the fire suppressors used at your developments and contact the manufacturer for replacement if your fire suppressors have been recalled, as there has already been an RHTC development where this failure occurred.



Recalled StoveTop FireStop Rangehood model number 675-3D

lame of product:

WilliamsRDM StoveTop FireStop Rangehood and Microhood Automatic Cooktop Fire Suppressors

Hazard:

The StoveTop FireStop (STFS) Rangehood and Microhood Automatic Cooktop Fire Suppressors can fail to activate the sealed openings that allow the suppressant powder to feed out of the canister and suppress the fire.

Remedy:

Replace

Recall date:

December 6, 2019

Units:

About 9,300 pairs









